

# Rennacs® CodeReader™ Diagnostic Test Results

**Grimmer Motors**  
998 Heaphy Terrace  
Fairfield, Hamilton, 3124  
<http://grimmermotors.co.nz>  
Ph: (07) 855 2037

---

**Operator:** CHARITH  
**Date:** 05/27/26  
**Time:** 15:35:23

**Customer:** GRIMMER  
**Vehicle:** Suzuki SUZUKI LIANA  
**Registration:** AJY797

**Invoice Number:** 0

---

Generic OBDII  
No fault codes present.

EFI  
No fault codes present.

Transmission  
No fault codes present.

ABS  
No fault codes present.

SRS  
B1032 Voltage Low for Supply

**Charge:** **No Charge**

**Total:** **No Charge**

---

CodeReader Information is Copyright © 2026 Rennacs Ltd  
Rennacs accept no liability for any mistake in, or misuse of this information.